SAMPLE REPORT Illustrative data showing the report format. Not an assessment of a real vehicle.

MARQUETRACE

VEHICLE RECORD | *Captured with MarqueCapture*

VEHICLE CONDITION REPORT

Record `MT-DEMO-1957-001`

Rubric visible-condition-v2



RECEIVED 12 OCT 2026, 21:14 UTC

1957 Porsche 356 A Coupé

Photographic condition review · Provisional

Stock photograph (Spencer Davis, Unsplash) for illustration. Not a captured vehicle, condition image or evidence file.

⚠ **Provisional AI findings — human review required.** This is a photographic review, not a mechanical inspection, appraisal, authenticity certificate or roadworthiness determination. LiDAR is retained but not analyzed by this report.

REQUIRED COVERAGE

15 / 16

required views captured

PHOTO-LINKED FINDINGS

6

1 Moderate · 3 Minor · 2 Uncertain

VISIBLE CONDITION

Good

Model confidence **0.64** · not a calibrated probability

MODEL SUMMARY


Paint, chrome and glass present well across the captured views. Two light marks on the left flank and a possible seam split on the driver seat need confirmation in person; glare limits the rear right three-quarter and gauge views.

VEHICLE	
Year	1957
Make	Porsche
Model	356 A Coupé
Visible condition	Good

RECORD	
Receipt	MT-DEMO-1957-001
Received	12 Oct 2026, 21:14 UTC
Report generated	12 Oct 2026, 21:16 UTC
Inspection SHA-256	8785fb35504d5a6cf8127c5dffc8b96af7a53777ab4b077f5196eeabc4448e6d

01 Photo-linked findings

EVIDENCE



Numbers mark the camera position of the photo each finding cites — the capture station, not a measured location on the panel.

01

MINOR Left Side Profile

Driver door, lower edge: two fine linear scratches about 4 cm long in the clear coat. Severity minor. Confirm under diffuse light before quoting refinishing.

Evidence `5a3c0000-0000-4000-8000-000000000004`

02

MINOR Front Left 3/4 Exterior

Front left wing at the wheel-arch lip: small stone chip exposing primer. Severity minor. Touch-up candidate; check the lip for corrosion creep.

Evidence `5a3c0000-0000-4000-8000-000000000002`

03

UNCERTAIN Rear Right 3/4 Exterior

Rear right quarter: a reflection band crosses the panel and may conceal a shallow dent. Severity uncertain. Retake at a lower angle under overcast light.

Evidence `5a3c0000-0000-4000-8000-000000000003`

04

MODERATE Interior - Front Cabin

Driver seat outer bolster: possible split along the piping seam. Severity moderate if confirmed. Inspect in person.

Evidence `5a3c0000-0000-4000-8000-000000000006`

05

MINOR Front Straight

Front bumper chrome: light pitting near the left overrider. Severity minor, cosmetic.

Evidence `5a3c0000-0000-4000-8000-000000000009`

06

UNCERTAIN Gauge Cluster / Odometer

Odometer face partly obscured by glare; the reading could not be confirmed. Severity uncertain. Retake straight-on with the lens shaded.

Evidence `5a3c0000-0000-4000-8000-000000000007`

02 Coverage and capture warnings

COVERAGE



15 of 16 required views captured.

15 accepted by a reviewer at capture.

VIN / Identity Plate	Front Left 3/4 Exterior
Rear Right 3/4 Exterior	Left Side Profile
Right Side Profile	Interior - Front Cabin
Gauge Cluster / Odometer	Engine Bay - Front / Top
Front Straight	Front Right 3/4 Exterior
Rear Straight	Rear Left 3/4 Exterior
Interior - Rear Cabin	Interior - Opposite Front Door
Engine Bay - Left Side	⚠ Engine Bay - Right Side

CAPTURE WARNINGS

⚠ 1 of 16 required views were not captured.

⚠ Key storage is self-reported metadata, not hardware attestation. A valid signature does not establish inspector or vehicle identity.

03 Limitations and recommended follow-up

⚠ LIMITATIONS

→ Raw LiDAR depth was retained but not analyzed, so dent depth is not measured.

→ Engine Bay - Right Side was not captured; no assessment of that area is possible.

→ Rear Right 3/4 and gauge views show strong glare; retake under overcast light.

→ The underside was not photographed; no assessment of corrosion below the sills or floor pans.

04 Report provenance

PROVENANCE

GENERATION RECORD	
Provider	anthropic
Model	claude-opus-5-5
Generated	12 Oct 2026, 21:16 UTC
Rubric version	visible-condition-v2
Inspection SHA-256	`8785fb35504d5a6cf8127c5dffc8b96af7a53777ab4b077f5196eeabc4448e6d`

Compare findings against the original inspection. Confirm uncertain marks in person and retake missing or unclear views before relying on this report.